EPA Water Compliance Inspection Report												
Section A: National Data System Coding (ie PCS)												
Transaction Code NPDES N 5 WVG610882				Mo/Day/Yr 1/13/14	Insp	pection ~	Туре	Inspector S		Facility Type 2		
Remarks: Inspection Work Days Facility Self-M Evaluation Rat						B1 QA					Reserved	
-	Section B: Facility Data											
Name and Location of Facility Inspected: Poca Blending, LLC Nitro, WV				<u>LC</u>	Section B.	Entry Tim					Permit Effective Date: 11/23/09	
Name(s) of On- SiteRepresentatives(s) Titles/Phone and Fax Numbers: Keith Beneker, Plant M (304) 741-7622				Plant M	<u>lanager</u>	Exit Time/I 1425/1-13-1					Permit Expiration Date: 03/31/14	
Name, Address of Responsible Official/Title/Phone/Fax: Poca Blending, LLC PO Box 713 Charleston, WV 25323					1	Contacted: Yes ⊠			No 🗌		Other Facility Data:	
	Section C: Areas Evaluated During Inspection M - Marginal; N - No; N/A - Not Applicable; N/E - Not Evaluated; S - Satisfactory; U - Unsatisfactory; Y - Yes											
S U	Permit Records/Report	Flow			Measurement oratory			oliance		_	erations & Maintenance dge Disposal	
U	Fac Site Review	v		Eff /	Rec. Waters	S	Schedule Self- Monitoring		U	Poll	Pollution Prevention	
	Pretreatment Groundwater D	ata	U		nwater ermitted	CSO/SSO				Mul	ltimedia	
Section D: Summary of Findings / Comments (attach additional sheets if necessary): Discharge Monitoring Reports (DMRs) were not available on site, but sample results were provided. No record of site inspections was maintained in the facility's plans, no spill log was maintained, and the only employee training record was from 2004. The plan indicates that the building itself acts as secondary containment, but holes exist at floor level in the building's walls. The building is surrounded by a trench which catches any runoff from within the building. Closed gates prevent this trench from discharging unless personnel open them, but since there is no method for separating stormwater from spillage prior to entering the trench, it does not function as secondary containment. Baker tanks containing MCHM from the recent Freedom Industries spill were staged on site. There were six tanks on site containing MCHM as well as additional empty tanks to be filled as cleanup continues. Compliance Assistance (check all that apply): Troubleshooting Records/Reports Sampling												
Name/Signature(s) of Inspectors(s) Kevin Saunders				Agency/Office/Telephone/Fax WVDEP/Environmental Enforcement/ P.O. Box 662 Teays, WV 25569 (304) 757-1693/(304) 757-3873				Date 1-13-14				
Signature of Management QA Reviewer Cynthia J. Musser				Agency/Office/Phone/Fax WVDEP/Environmental Enforcement/ P.O. Box 662 Teays, WV 25569 (304) 757-1693/(304) 757-3873			Date 1/14/14					

EPA Form 3560-3 Revised: October 2003

Rev.3 11/10 rh/jc/jh

STATE OF WEST VIRGINIA DEPARTMENT OF ENVIRONMENTAL PROTECTION ENVIRONMENTAL ENFORCEMENT

Permit	WV0111457				
Reg. #	WVG610882				

INDUSTRIAL STORMWATER FACILITY INSPECTION REPORT

Tr. 4		D1 1	: !! 6	, <u> </u>				ON. N	: W/W/					
	FACILITY NAME: Poca Blending, LLC LOCATION: Nitro, WV													
PERMIT EXPIRATION: 3-31-14					COUNTY: Putnam				utnam					
DA	TE INSPECTED:	1-13-1	4	WEA	THE	R: _c	lear			T	IME IN:	1030		
PEF	RMITTEE: Poca Blen	ding, LI	LC							T	IME OUT:	1425		
ADI	P.O. Box	713, Ch	arleston,	WV 2	25323	3								
FA(CILITY EVALUATION	l:		No l	Expo	sure 🗌			Lov	Low concentration waiver				
	Permit		Rating				GPP		Rating		SWP	PP conti	nued	Rating
1	Separate SW / Waste s	ewers	S	13	Plar	n retaine	d on site		S	24	Semi-ann	ual discha	rge insp	U
02	General Housekeeping		M	14			orage an		U	25	Annual sit			U
03	Trash Disposal		M			•	Containm	ent		26	Benchmar			Yes
04	Tire Disposal		N/A	15		tery Stor			N/A	27	Plan modi			N/D
05	Sludge Disposal		N/A	16	` ' 1			U	28	GPP & SW		t permit	M	
06	Garage fluids handling		N/A		SWPPP			~		requiremen				
07	Sanitary waste disposal		S	17				S	20		Records		**	
08	Non-Stormwater discha	ırges	N/O	18	Ŭ			N/A	29	DMR's			U	
09	Oil / Water Separator		N/D	19				N/A	30	Spills / Re		1 .	U	
10	Operation & Maintenar		U	20				N/A	31	_	Self inspection / Records Sampling			
11	Representative samplin	g	N/D	21	1			U	32	Employee Training			N/D	
12	TMDL / 303 (d) listed str	ream	N/A	22				3MP's	U M	33 34	Other			U
	*Rating: S-Satisfactory	M-Mai	rainal II			ll Respon	nse kit -Not Appli	coblo N	O-Not Obs		N/D-Not De	tormined T	hic Vicit	
OU	FLET EVALUATION:	141-14141	igiliai U	-Onsat	1514010	ny IVA	-Not Appn	icable 14	70-110t Obs	sei veu	IVD-NOT DE	termineu 1	IIIS VISIT	
	Outlet Number	001	002	00	03	004								
	Appearance	N/D	N/D											
	Marker	No	No										Ì	
SAM CCC situt 200 sec annis 1 A cool in to wee ma ma Ba cool pro and	RECEIVING STREAM: Kanawha River SAMPLES TAKEN: Yes No X PHOTOS TAKEN: Yes X No COMMENTS: Discharge Monitoring Reports (DMRs) were not available on site, but sample results were provided. No record of site inspections was maintained in the facility's plans, no spill log was maintained, and the only employee training record was from 2004. Secondary containment within the facility was deteriorated or nonexistent. The plan indicates that the building itself acts as secondary containment, but holes exist at floor level in the building's walls. The building is surrounded by a trench which catches any runoff from within the building. Closed gates prevent this trench from discharging unless personnel open them, but since there is no method for separating stormwater from spillage prior to entering the trench, it does not function as secondary containment. A variety of chemicals (emulsifiers, oxidizers, acids, corrosives, mineral oil, etc) were stored in the facility without secondary containment and could reach the trench in the event of a spill. When solids are cleaned out from this trench, they are disposed of in the regular waste stream. Due to the potential contamination of this material, it should be treated as a special waste. Upgrades to secondary containment are planned for the oil/petroleum containers in the facility, but not the other chemicals. No spill kits were observed at this facility, but on site personnel stated that oil absorbent material was available throughout the facility. Scrap material and solid waste were observed behind the building and on site personnel were instructed to properly dispose of this material. Baker tanks containing MCHM from the recent Freedom Industries spill were staged on site. There were six tanks on site containing MCHM as well as additional empty tanks to be filled as cleanup continues. Construction of a clay berm is planned to provide secondary containment for these tanks, but two are currently placed in a location which would prevent such construction and only one tank													
Insp	Inspector: 3-3-1							Т	Celeph	none:	ae: <u>304-757-1693</u>			
Cor	Company Official: Title:													
Nui	nber of NOV's issue	d this	date: <u>5</u>		NO	ONE:								

NOTICE OF VIOLATION

Violation No. <u>**I14-20-001-EJP**</u>

To the Operator or Agent of:								
Facility Name: Poca Blending	, LLC Permit No. WVG6108	3 <u>82</u>						
Permittee or Individual Poca B	lending, LLC.							
Located at or near Nitro in I	Kanawha County							
Representative Keith Beneker	Representative Keith Beneker, Plant Manager Date 01/13/2014 Time 10:30							
Address / phone number P.O. J	Box 713, Charleston, WV 253	<u>223</u>						
Secretary, at which the following Article 11, Section(s) 1 et seq. 6	g described condition or praction of the Code of West Virginia a ection A. (Monitoring Requi	ndersigned, duly authorized agent of the ce exists, in violation of Chapter 22, nd/or Section(s) of the Rules and rements) of the Permit referenced above						
Failed to prvovide Discharge	Monitoring Reports Indication	ng in terms of concentration, the values of the						
constituents listed in Part A a	nalytically determined to be i	n the effluent for the 1 st half 2012, 2 nd half						
2012, and 1 st half of 2013.								
actions taken to abate this viola	-	ned below, at the address indicated, detailing the						
Received by:								
Eu Phfu	gnature	Title						
Eric J. Philyaw								
Duly Authorized Agent / 304-757-1693 Eric.J.Philyaw@wv.gov								
Inspector Telephone E-mail								
Send Response to the Inspecto	or at the address indicated be	low:						
WV Department of Environmen								
Environmental Enforcement / V								
PO Box 662, Teays, WV 25569	O Box 662, Teays, WV 25569							

STATE OF WEST VIRGINIA Department of Environmental Protection

Environmental Enforcement

NOTICE OF VIOLATION

Violation No. <u>114-20-002-EJP</u>		
To the Operator or Agent of:		
Facility Name: Poca Blending ,	LLC Permit No. WVG6108	<u>82</u>
Permittee or Individual Poca Blo	ending, LLC.	
Located at or near Nitro in K	anawha County	
Representative Keith Beneker,	Plant Manager Date 01/13	3/2014 Time 10:30
Address / phone number P.O. B	ox 713, Charleston, WV 253	<u>23</u>
Secretary, at which the following Article 11, Section(s) 1 et seq. of Regulations and/or Section(s)	g described condition or practical of the Code of West Virginia arection B.17 (Stormwater Pollicenced above promulgated therectormwater Pollution Prevent Inspections (GPP) The production of the production of the production of the production of the product of the production of the	ion Plan and Groundwater Protection Plan. ollution prevention devices (SWPPP) enchmark pollutant concentrations (SWPPP)
Received by:		
Erin Phylin	nature	Title
Eric J. Philyaw Duly Authorized Agent /		Eric.J.Philyaw@wv.gov
Inspector	Telephone	E-mail

Send Response to the Inspector at the address indicated below:

WV Department of Environmental Protection Environmental Enforcement / WW PO Box 662, Teays, WV 25569

NOTICE OF VIOLATION

Violation No. I14-20-003-EJP To the Operator or Agent of: Facility Name: Poca Blending, LLC Permit No. WVG610882 Permittee or Individual **Poca Blending, LLC.** Located at or near **Nitro** in **Kanawha**County Representative Keith Beneker, Plant Manager Date 01/13/2014 Time **10:30** Address / phone number P.O. Box 713, Charleston, WV 25323 Whereas, an inspection of the above named operation by the undersigned, duly authorized agent of the Secretary, at which the following described condition or practice exists, in violation of Chapter 22, Article 12, Section(s) 1 et seq. of the Code of West Virginia and/or Section(s) 47CSR58-4.7.d of the Rules and Regulations and/or Section(s) of the Permit referenced above promulgated thereunder in that you: Failed to store drums containing materials that have the potential to contaminate groundwater so that spills and leaks are contained. Within 20 days provide a written response to the inspector named below, at the address indicated, detailing the actions taken to abate this violation. Received by: Signature Title Eric J. Philyaw Duly Authorized Agent / Eric.J.Philyaw@wv.gov Inspector Telephone E-mail

Send Response to the Inspector at the address indicated below:

WV Department of Environmental Protection Environmental Enforcement / WW PO Box 662, Teays, WV 25569

NOTICE OF VIOLATION

Violation No. <u>I14-20-004-EJP</u>						
To the Operator or Agent of:						
Facility Name: Poca Blending, I	LC Permit No. WVG610	<u>882</u>				
Permittee or Individual Poca Ble	nding, LLC.					
Located at or near Nitro in Ka	<u>nawha</u> County					
Representative Keith Beneker, F	Plant Manager Date 01/1	13/2014 Time 10:30				
Address / phone number P.O. Bo	x 713, Charleston, WV 25	323				
Secretary, at which the following Article <u>12</u> , Section(s) <u>1 et seq.</u> of	described condition or practhe Code of West Virginia	undersigned, duly authorized agent of the tice exists, in violation of Chapter <u>22</u> , and/or Section(s) <u>47CSR58-4.8.a</u> of the Rules and above promulgated thereunder in that you:				
Above Ground Storage Tanks w	vere not provided with ap	propriate secondary containment.				
Within <u>20</u> days provide a written actions taken to abate this violation		med below, at the address indicated, detailing the				
Received by:						
Eru Phylur	nature	Title				
Eric J. Philyaw	-					
Duly Authorized Agent / Inspector	• • • • • • • • • • • • • • • • • • • •					
_	Telephone					
Send Response to the Inspector WV Department of Environmenta		elow:				

Environmental Enforcement / WW PO Box 662, Teays, WV 25569

NOTICE OF VIOLATION

Violation No. <u>I14-20-005-EJP</u>							
To the Operator or Agent of:							
Facility Name: Poca Blending,	LLC Permit No. WVG610	<u>9882</u>					
Permittee or Individual Poca Bl	ending, LLC.						
Located at or near Nitro in K	anawha County						
Representative Keith Beneker,	Plant Manager Date 01/2	13/2014 Time 10:30					
Address / phone number P.O. E	Sox 713, Charleston, WV 25	<u> </u>					
Secretary, at which the following Article 11, Section(s) 1 et seq. or Regulations and/or Section(s) A thereunder in that you: Failed to post a permanent mate Section 9 of the West Virginia Within 20 days provide a written actions taken to abate this violate	g described condition or prace of the Code of West Virginia ppendix A.I.13 (Outlet Manager at each permitted out Legislative Rules. The response to the inspector national description of the condition of the code of the c	undersigned, duly authorized agent of the tice exists, in violation of Chapter 22, and/or Section(s) of the Rules and reserved above promulgated fall in accordance with Title 47, Series 11, amed below, at the address indicated, detailing the					
Received by:							
Em Phylin	gnature	Title					
Eric J. Philyaw Duly Authorized Agent / 304-757-1693 Eric.J.Philyaw@wv.gov							
Inspector Telephone E-mail							
Send Response to the Inspecto	r at the address indicated b	elow:					
WV Department of Environment Environmental Enforcement / W							
PO Box 662, Teays, WV 25569	,,						